

LOADED KNUCKLES

SUSPENSION & STEERING KNUCKLE KITS

DORMAN

The Latest Innovation from the Aftermarket's Knuckle Experts

With the Most Comprehensive Coverage Available



698-012

Ford Explorer, Mercury Mountaineer 2005-02

Loaded Knuckles are pre-pressed knuckle assemblies with everything included for an easy repair. Rear applications come pre-assembled with parking brake shoes and hardware **(DORMAN EXCLUSIVE!)**

- The technician-preferred, bolt-on solution that can save 90+ minutes when replacing difficult Gen-1 (press-in) bearings
- Never again worry about damaging individual components during hub removal
- Press-free solution opens up the job to all repair facilities
- Dorman will grow the Aftermarket with dozens of New to the Aftermarket SKUs

FAILURE MODE:

- Bearing failure - Bearings typically wear out between 75-150K miles
- Knuckle failure - Often damaged by collisions, potholes, and curb strikes
- Rust

LOADED KNUCKLE COMPONENTS



AUTO PARTS

Benson

PIÈCES D'AUTO

LOADED KNUCKLES

SUSPENSION & STEERING KNUCKLE KITS

DORMAN

**DORMAN OFFERS 4X MORE
LOADED KNUCKLES THAN THE
NEXT LEADING COMPETITOR**

L/C=RBI LOADED KNUCKLE COVERAGE

NATIONAL SALES RANK	APPLICATIONS	DORMAN # (LEFT)	DORMAN # (RIGHT)	VIO COUNT US	VIO COUNT CANADA
1	2017-12 Toyota Camry	698-383	698-382	2,165,569	92,242
2	2012-05 Ford Escape, Mercury Mariner, Mazda Tribute	698-405	698-404	1,554,947	255,806
3	2012-06 Ford Fusion, Lincoln Zephyr, Mercury Milan, 2012-07 Lincoln MKZ	698-409	698-408	1,511,814	116,579
4	2005-02 Ford Explorer, Mercury Mountaineer	698-013	698-012	1,282,776	42,311
5	2010-06 Ford Explorer	698-413	698-412	478,114	26,656
6	2010-98 Volkswagen Beetle, Golf, 2005-99 Jetta, 2000-99 GTI	698-375	698-374	765,554	198,774
7	2016-09 Toyota Corolla, Matrix	698-381	698-380	2,501,085	478,442
8	2004-01 Ford Escape	698-377	698-376	378,059	33,971
9	2008-03 Toyota Matrix	698-385	698-384	254,897	11,186
10	2001-97 Toyota Camry	698-391	698-390	820,821	55,631
11	2017-12 Toyota Camry, 2016-13 Avalon	698-397	698-396	2,409,768	96,422
12	2006-04 Toyota Camry	698-399	698-398	619,584	30,095
13	2007-03 Honda Accord; Auto Trans	698-401	698-400	547,061	79,575
14	2011-06 Ford Focus	698-407	698-406	821,000	118,481
15	2012-08 Dodge Caliber	698-411	698-410	867,434	133,324
16	2008-03 Toyota Corolla	698-389	698-388	1,297,106	268,291
17	2006-02 Nissan Altima; 2.5L Eng	698-379	698-378	711,568	65,317
18	2006-02 Nissan Altima; 3.5L Eng	698-423	698-422	129,932	13,513
19	2007-03 Honda Accord; Manual Trans	698-403	698-402	547,061	79,575
20	2011-05 Toyota Avalon	698-393	698-392	329,365	6,468

ALSO AVAILABLE: BARE KNUCKLES

Dorman Aftermarket-Exclusive Category with 145+ SKUs Covering Over 92 Million VIO in US/Canada



698-082

Lexus 2012-04, Toyota 2017-04



698-024

Honda Civic 2011-06

- Failure is due to rust-related issues, collision & caliper mount-area wear
- Matches OE fit and function

COMING SOON: MORE LOADED KNUCKLES SKUS to be released later this year

Applications	RBI Left #	RBI Right #
1 2013-07 Mazda CX-7	698-414	698-415
2 2008-01 Subaru Forester (disc)	698-416	698-417
3 2008-01 Subaru Forester (drum)	698-418	698-419
4 2001-97 Toyota Camry; 2.2L Eng (with 14" wheels)	698-420	698-421
5 Toyota: Highlander (2006-2007, Hybrid); Lexus: RX330/RX350 (2004-2009), RX400/RX400H (2006-2008)	698-426	698-427
6 2007-01 Toyota Highlander 4 cyl	698-442	698-443
7 2007-01 Toyota Highlander 6 cyl	698-444	698-445
8 2013-11 Ford Transit Connect	698-466	698-467
9 2001-97 Toyota Camry; 2.2L Eng (with 15" wheels)	698-472	698-473
10 2017-13 Honda Accord	698-474	698-475

AUTO PARTS

Benson

PIÈCES D'AUTO

Le dernier cri des experts en moyeux pour suspension et direction
avec la meilleure couverture comprehensive disponible sur le marché secondaire



698-012

Ford Explorer, Mercury Mountaineer 2005-02

Les ensembles de moyeux pour suspension/direction sont pré-assemblés et comprennent tout dont vous avez besoin pour une réparation facile. Les applications arrière sont également pré-assemblées avec les sabots de freins et la quincaillerie (**exclusif à DORMAN!**)

- La solution préférée par les techniciens lorsqu'ils remplacent des roulements Gen-1 qui sont difficiles à enlever...signifie une épargne de 90+ minutes
- Ne craignez plus jamais d'endommager des pièces individuelles lors du retrait du moyeu
- Une solution sans presse ouvre le travail à toutes les ateliers de réparation
- Dorman développera le marché des pièces de rechange avec des dizaines de nouvelles unités sur le marché des pièces de rechange

Mode de défaillance

- Défaillance du roulement - les roulements s'usent généralement entre 75 à 150,000KM
- Défaillance de la fusée d'essieu et du support de montage: souvent endommagé par des collisions, des nids-de-poule et des colliers d'arrêt
- Rouille

PIÈCES RETROUVÉES DANS L'ENSEMBLE DE MOYEU



ENSEMBLES DE MOYEURS POUR SUSPENSION & DIRECTION

DORMAN

**DORMAN OFFRE 4X PLUS DE
LOADED KNUCKLES QUE CES
COMPÉTITEURS**

COUVERTURE DES ENSEMBLES DE MOYEURS

RACI VENTES NAT.	RBI APPLICATIONS	DORMAN # (GAUCHE)	DORMAN # (DROITE)	VIO COUNT ÉTATS-UNIS	VIO COUNT CANADA
1	2017-12 Toyota Camry	698-383	698-382	2,165,569	92,242
2	2012-05 Ford Escape, Mercury Mariner, Mazda Tribute	698-405	698-404	1,554,947	255,806
3	2012-06 Ford Fusion, Lincoln Zephyr, Mercury Milan, 2012-07 Lincoln MKZ	698-409	698-408	1,511,814	116,579
4	2005-02 Ford Explorer, Mercury Mountaineer	698-013	698-012	1,282,776	42,311
5	2010-06 Ford Explorer	698-413	698-412	478,114	26,656
6	2010-98 Volkswagen Beetle, Golf, 2005-99 Jetta, 2000-99 GTI	698-375	698-374	765,554	198,774
7	2016-09 Toyota Corolla, Matrix	698-381	698-380	2,501,085	478,442
8	2004-01 Ford Escape	698-377	698-376	378,059	33,971
9	2008-03 Toyota Matrix	698-385	698-384	254,897	11,186
10	2001-97 Toyota Camry	698-391	698-390	820,821	55,631
11	2017-12 Toyota Camry, 2016-13 Avalon	698-397	698-396	2,409,768	96,422
12	2006-04 Toyota Camry	698-399	698-398	619,584	30,095
13	2007-03 Honda Accord; Auto Trans	698-401	698-400	547,061	79,575
14	2011-06 Ford Focus	698-407	698-406	821,000	118,481
15	2012-08 Dodge Caliber	698-411	698-410	867,434	133,324
16	2008-03 Toyota Corolla	698-389	698-388	1,297,106	268,291
17	2006-02 Nissan Altima; 2.5L Eng	698-379	698-378	711,568	65,317
18	2006-02 Nissan Altima; 3.5L Eng	698-423	698-422	129,932	13,513
19	2007-03 Honda Accord; Manual Trans	698-403	698-402	547,061	79,575
20	2011-05 Toyota Avalon	698-393	698-392	329,365	6,468

ÉGALEMENT DISPONIBLE: SUPPORT POUR MOYEU

Catégorie exclusive au marché secondaire de Dorman avec plus de 145 SKU couvrant plus de 92 millions de VIO aux États-Unis et au Canada



698-082

Lexus 2012-04, Toyota 2017-04



698-024

Honda Civic 2011-06

- Défaillance occasionnée par des problèmes de rouille, collision et l'usure de l'étrier et/ou le support de montage
- Exactement comme la pièce d'origine quant à l'apparence, la taille et la fonction
- Comprend de nouvelles bagues et rotules, lorsque applicable

À VENIR BIENTÔT! D'AUTRES ENSEMBLES DE MOYEURS POUR SUSPENSION

Seront introduits plus tard cette année

Applications	RBI Left #	RBI Right #
1 2013-07 Mazda CX-7	698-414	698-415
2 2008-01 Subaru Forester (disc)	698-416	698-417
3 2008-01 Subaru Forester (drum)	698-418	698-419
4 2001-97 Toyota Camry; 2.2L Eng (with 14" wheels)	698-420	698-421
5 Toyota: Highlander (2006-2007, Hybrid); Lexus: RX330/RX350 (2004-2009), RX400/RX400H (2006-2008)	698-426	698-427
6 2007-01 Toyota Highlander 4 cyl	698-442	698-443
7 2007-01 Toyota Highlander 6 cyl	698-444	698-445
8 2013-11 Ford Transit Connect	698-466	698-467
9 2001-97 Toyota Camry; 2.2L Eng (with 15" wheels)	698-472	698-473
10 2017-13 Honda Accord	698-474	698-475

AUTO PARTS

Benson

PIÈCES D'AUTO